

## **Trailer Suspensions**



# DOCKMASTER SLIDER SUSPENSION

### **Visual Inspection**

- Check for loose or missing fasteners.
- 2. Check for Cracks in hangers, trailing arms and axle connection.
- 3. Check air springs for abrasions and punctures.
- 4. Check torque on pivot bolts and shock bolts.

### **Torque Requirements**

- 1. Tighten NUT side of pivot bolt to 400-425 ft lbs (542-576 Nm).
- 2. Tighten BOLT HEAD side of pivot bolt to 700-750 ft lbs (949-1017 Nm).
- 3. Tighten the Rey-Align to 60 ft lbs (81 Nm).
- 4. Tighten the shock absorber bolts to 175-200 ft lbs (237-271 Nm).
- 5. Tighten the upper 1/2" air spring nuts to 25-30 ft lbs (34-41 Nm).
- 6. Tighten the upper 3/4" spring retainer nuts to 25-30 ft lbs (34-41 Nm).
- 7. Tighten the lower 3/8" spring retainer nuts to 15-20 ft lbs (20-27 Nm).
- 8. Tighten 1/4" air valve linkage nut to 5 ft lbs (7 Nm).

#### **Recommended Maintenance Schedules**

- 1. Perform pre-service visual inspection (as outlined above).
- 2. Perform visual inspection after 1,000 3,000 miles (1609-4828 Km).
- 3. Perform visual inspection and Preventive Maintenance inspections, concurrent with DOT "C" inspections, annually.
- 4. Perform visual inspection during the replacement of any service parts.
- 5. Perform visual inspection upon discovery of any loose components.

If any of the above defects are noted, have vehicle checked by a qualified mechanic. Torque values are specified with clean, lightly oiled fasteners, and should only be verified with a calibrated torque wrench. Failure to follow these instructions could void the warranty and could result in subsequent injury.

Lb-ft = Foot - Pounds; Nm = Newton - Meters

1-800-753-0050 www.reycogranning.com

Reyco Granning Suspensions 1205 Industrial Park Drive

Mount Vernon, MO 65712 Phone: 417-466-2178 Fax: 417-466-3964