

Product Bulletin #: 2033
Model: 86AR Suspensions
Topic: New Spring Beam Hardware Kits
Effective Date: August 17, 2000
ECR #: 11915

Reyco Granning now has two new spring beam hardware kits for the 86AR suspensions. When replacing the spring beam, the following hardware is required to re-attach the lower air spring support and the track rod brackets.

K700560 Hardware kit for 19913-01 (left side) Spring Beam consists of:
(5) 17353-01 1/2" bolt
(5) 17357-01 1/2" locknut
(5) 0003-07 1/2" washer
(1) 18842-01 7/8" bolt
(1) 14345-01 7/8" locknut
(1) T7292 washer

K700561 Hardware kit for 19914 01 (right side) Spring Beam consists of:
(1) 17353-01 1/2" bolt
(1) 17357-01 1/2" locknut

Please call your Customer Account Representative for pricing and additional information.

1-800-753-0050
www.reycogranning.com

Reyco Granning Suspensions
1205 Industrial Park Drive
Mount Vernon, MO 65712